



Maralex location ID  
Mollie – Crynee Photo document  
10/1/2024



10.01.2024

Tank and equipment not compliant  
with visual mitigation rule





Maralex Resources, Inc  
970-563-4000  
Emergency Services - 911

MOLLIE CORYNNE 33-7-2 #2A

API# 05-067-08800 COC66499  
Access from County Road 334  
La Plata County  
NENE Sec 2 T33N R7W  
Lat: 37.13708 Long: -107.57148

10.01.2024





Muffler leaking oily substance onto  
bare ground

10.01.2024





2A wellhead

10.01.2024









10.01.2024

3C wellhead





10.01.2024





10.01.2024



## Inspection Photos

Location Name:

Location ID:



No calibration record displayed for 2A well 4/15/24



No calibration record displayed for 2A well 10/1/24





Soil pile near 3C meter house



## Inspection Photos

Location Name:

Location ID:



No calibration record for 3 C well displayed 4/15/24



No calibration record for 3C well displayed 10/1/24





10.01.2024





Tank labeling indicating flammable  
condensate

10.01.2024







## Inspection Photos

Location Name:

Location ID:



Tank labeling 4/15/24



Tank labeling 10/1/24 with zero for flammability in NFPA diamond





**WARNING**  
DANGER  
HARMFUL CONDENSATE  
UNDER PRESSURE  
CAUTION: AFTER RATED TO RELIEVE GAS  
PRESSURE OF BEFORE LOADING INTO TANK.

10.01.2024





10.01.2024





10.01.2024

Equipment removed from interim  
revegetation area





Fence posts