

Inspection Photos

October 8th, 2024

Operator: Williford Resources - 96735

Location ID: 325151

Inspection Document #: 714001328

La Plata County, CO

Township: NWNW 13 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dye Hard 1
Location ID: 325151



Photo 1. 067-05446view of the well pad taken from the northern edge facing center.

Inspection Photos
Location Name: Dye Hard 1
Location ID: 325151



Photo 2. View of weedy Kochia debris/vegetation encroaching on well head.



Inspection Photos
Location Name: Dye Hard 1
Location ID: 325151



Photo 3. Associated remote tank battery.



Inspection Photos
Location Name: Dye Hard 1
Location ID: 325151

10/8/24
+37.109071,-108.109857
8° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of the interim reclamation area surrounding pump jack. Area is dominated by perennial grasses and desirable vegetation including but not limited to Rubber Rabbitbrush and Crested Wheatgrass.

API #: 067-05446

Inspection Photos
Location Name: Dye Hard 1
Location ID: 325151



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Sagebrush, Rubber Rabbitbrush and Indian Ricegrass.

API #: 067-05446