

Final Reclamation and Stormwater Inspection

Date: 10/16/24

Operator: City & County of Denver - 17320

Location ID: 320272

Inspection Document #: 713901111

Adams County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Liberty #1
Location ID: 320272



Photo 1. The photo was taken at the tank battery location facing Northwest. The photo illustrates the location is dominated by kochia and russian thistle with some scotch thistle.

Photo 2. The photo was taken at the tank battery location facing North. The photo illustrates the western side of the tank battery facility is dominated by cereal rye, russian thistle with common mullein and scotch thistle.

Inspection Photos
Location Name: Liberty #1
Location ID: 320272



Photo 3. The photo was taken at the well location facing North. The photo illustrates weeds dominating the well location consisting of scotch thistle and cereal rye.



Photo 4. The photo was taken at the well location facing East. Refer to the comment for photo 3.

Inspection Photos
Location Name: Liberty #1
Location ID: 320272



Photo 5. The photo was taken at the well location facing South. Refer to the comment for photo 3.

Photo 6. The photo was taken at the well location facing West. Refer to the comment for photo 3.

Inspection Photos
Location Name: Liberty #1
Location ID: 320272



Photo 7. The photo was taken along the access road to the well location facing Southeast. Refer to the comment for photo 3.