

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 10/21/2024



Northwest Corner of Location – Photo #04305



Wellheads – Photo #04303

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 10/21/2024



Separators – Photo #04306



Separators – Photo #04307



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 10/21/2024



Tank Battery – Photo #04309



ECD/Meter – Photo #04308



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, FEDERAL HAGEN-67S95W/16NESE

Location ID: 335041

Date: 10/21/2024



**Lack of Stabilization/Degradation – Photo #04304**



**Insufficient Tracking BMPs – Photo #04310**