

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 10/21/2024



Location Entrance – Photo #04313



Wellheads – Photo #04314

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 10/21/2024



Oct 21, 2024 at 12:08:59
1632 Underwood Ln
Parachute CO 81635
United States

Separators – Photo #04316



Oct 21, 2024 at 12:12:00
1632 Underwood Ln
Parachute CO 81635
United States

Tank Battery – Photo #04321

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 10/21/2024



Gas Meter – Photo #04319



Open-Ended Line – Photo #04318

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 10/21/2024



Lack of Stabilization – Photo #04315



Lack of Stabilization – Photo #04323

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SHORE-67S95W/16NWSE

Location ID: 334656

Date: 10/21/2024



Insufficient Tracking BMPs – Photo #04324