

Inspection Photos

API: 073-06583

Operator: **GRAND MESA OPERATING CO**

Inspection Date: 10/21/2024

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the access road. The cattle guard remains and the road has not been reclaimed.



Inspection Photos



Photo 2. Facing south along the access road that has not been regraded and reclaimed. There are signs of erosion along the road and undesirable weeds.



Inspection Photos



Photo 3. Facing south along the access road near the location. There are signs of erosion along the road which is not stabilized.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:436429 | Date: 10/21/2024

Inspection Photos



Photo 4. Facing southeast at the location which is fenced.



Inspection Photos



Photo 5. Facing southeast at the reclaimed location. The perennial vegetation is progressing well throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:436429 | Date: 10/21/2024

Inspection Photos



Photo 6. Facing south at the reclaimed location. The perennial vegetation is progressing well throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:436429 | Date: 10/21/2024

Inspection Photos



Photo 7. Facing northwest. The brown vegetation is undesirable weeds. Additional seeding and mowing of this area would be beneficial.

