

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 Pad

Location ID: 335289



Photo # 6626 From entrance to location



Photo # 6627 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 Pad

Location ID: 335289



Photo # 6628 Location



Photo # 6629 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 Pad

Location ID: 335289



Photo # 6630 Location



Photo # 6631 Capacity on tank label faded & illegible/tank label does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 Pad

Location ID: 335289




Photo # 6632 Capacity on tank label faded & illegible/tank label does not comply with CECMC rules



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources