

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2024

Submitted Date:

10/15/2024

Document Number:

713601518

FIELD INSPECTION FORMLoc ID 321049 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 16830

Name of Operator: CHOLLA PRODUCTION LLC

Address: 10390 BRADFORD RD #201

City: LITTLETON State: CO Zip: 80127

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments
2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goff, Bill	303-249-0430	cholla_production@msn.com	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205866	WELL	PA	11/17/2010	GW	009-06281	TATE 1-10	RI

General Comment:

This is a reclamation inspection of the TATE #1-10 location.
See attached photos and additional details within this report.

Environmental			
Spills/Releases:			
Type of Spill: _____		Estimated Spill Volume: _____	
Comment:		<div>The associated tank battery site located 600' east of the wellsite has not established vegetation and appears to have impacted soils.</div>	
Corrective Action:		<div>Submit Form 19 to report historic spill of impacted material per Rule 912.b.</div>	
		Date: 10/23/2024	
Reportable: _____		GPS: Lat _____ Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well Complaint:			
		Lat _____ Long _____	
DWR Receipt Num: _____		Owner Name: _____ GPS : _____	
Field Parameters:			
<div></div>			
Sample Location: _____		Comment: _____	

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: The crop appears to be established at the abandoned wellsite. The associated tank battery site located 600' east of the wellsite has not established vegetation and appears to have impacted soils. The associated tank battery site will require soil sampling, remediation, and reclamation. Any impacted soils should be removed and replaced with suitable topsoil for reclamation.

Corrective Action:	Comply with 1004 Rules	Date	03/01/2025
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403959411	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6748568
713601519	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6748561