

Inspection Photos

API: 017-07386

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the location. There are areas of bare compacted soils that need to be reclaimed.



Inspection Photos



Photo 2. Facing southeast at the location. There is a pile of gravel that needs to be removed.



Inspection Photos



Photo 3. Facing northeast at the location. There is a black hardened waste that needs to be removed shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321901 | Date: 10/21/2024

Inspection Photos



Photo 4. There is a black hardened waste that needs to be removed.



Inspection Photos



Photo 5. Facing northeast at the location. There are areas of bare compacted soils that need to be reclaimed.



Inspection Photos



Photo 6. West side of the location facing southeast. Facing east at the location. There are posts and cement debris that needs to be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:321901 | Date: 10/21/2024