

# Inspection Photos

API: 017-07227

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2024

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing north toward the access road which has not been recontoured and reclaimed.





## Inspection Photos



**Photo 2.** Facing southwest at the location. There are areas at the south side of the location that are bare of vegetation and undesirable weeds. This is where the former drilling pit was located.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321873 | Date: 10/21/2024



## Inspection Photos



**Photo 3.** Facing southwest at the location. This bare area is approximately 75 ft. by 20 ft.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321873 | Date: 10/21/2024



## Inspection Photos



**Photo 4.** South side of the location facing northwest.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321873 | Date: 10/21/2024



## Inspection Photos



**Photo 5.** South side of the location facing northwest. There are areas of bare soil and undesirable weeds at the south side where the former drilling pit was located.





## Inspection Photos



**Photo 6.** West side of the location facing southeast.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321873 | Date: 10/21/2024



## Inspection Photos



**Photo 7.** Facing east at the former wellsite. This area has compacted soils that need to be cross ripped.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:321873 | Date: 10/21/2024



## Inspection Photos



**Photo 8.** Facing east toward the surrounding undisturbed rangeland.

