

Inspection Photos

API: 017-07232

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 10/21/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the access road which has not been reclaimed.



Inspection Photos



Photo 2. The access road is not recontoured and reclaimed. There is erosion occurring along this area of the road.



Inspection Photos



Photo 3. Facing southwest toward the location. The location has not been reclaimed.



Inspection Photos



Photo 4. Facing southwest at the location. There are areas with no vegetation and soils have not been recontoured and decompacted.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321876 | Date: 10/21/2024

Inspection Photos



Photo 5. West side of the location facing east.

