

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: MCINTYRE CANYON UNIT #6-H-18

Location ID: 316804

API #: 05-113-06011

Inspection Date: 10/22/2024

Inspection Doc#: 693807845



Wellhead with fence and sign



Separator and Meter

Inspection Photos

Operator: AMERICAN HELIUM OPERATING LLC - 10841

Location Name: MCINTYRE CANYON UNIT #6-H-18

Location ID: 316804

API #: 05-113-06011

Inspection Date: 10/22/2024

Inspection Doc#: 693807845



Tank battery removed



Location overview looking W