

Inspection Photos

October 22nd, 2024

Operator: Logos Operating LLC - 10679

Location ID: 325181

Inspection Document #: 714001377

La Plata County, CO

Township: SENW 36 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-10 6
Location ID: 325181

10/22/24
182° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the northern edge facing center.

API #: 067-05569

Inspection Photos
Location Name: Bondad 33-10 6
Location ID: 325181



Photo 2. Cardinal views taken from the center of the disturbance, left photo facing north, right photo facing east.

Inspection Photos
Location Name: Bondad 33-10 6
Location ID: 325181



Photo 3. Cardinal views taken from the center of the disturbance, left photo facing south, right photo facing west. Note: Weedy Kochia and Russian Thistle debris observed in large patches throughout the project area that are interfering with establishment of desirable vegetation.

Inspection Photos
Location Name: Bondad 33-10 6
Location ID: 325181



Photo 4. Weedy Kochia and Russian Thistle debris observed on location.

Inspection Photos

Location Name: Bondad 33-10 6

Location ID: 325181



Photo 5. View of the access road that remains un reclaimed with bare soils, erosion issues and remnant rocks/gravel. Additional reclamation work along the access road is needed.

Inspection Photos
Location Name: Bondad 33-10 6
Location ID: 325181



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Big Sagebrush, Sand Dropseed and Western Wheatgrass.

API #: 067-05569