

# Inspection Photos

October 22nd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326180

Inspection Document #: 714001380

La Plata County, CO

Township: SESE 10 33N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: FC Armstrong 001 1  
Location ID: 326180



Photo 1. View of the well pad taken from the access point facing center.





Inspection Photos  
Location Name: FC Armstrong 001 1  
Location ID: 326180



**Photo 2.** View of weedy Kochia debris observed on the active pad.



Inspection Photos  
Location Name: FC Armstrong 001 1  
Location ID: 326180

10/22/24  
222° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of the western interim reclamation area composed of Intermediate Wheatgrass, Rubber Rabbitbrush and Sand Dropseed.

API #: 067-07610



Inspection Photos  
Location Name: FC Armstrong 001 1  
Location ID: 326180



**Photo 4.** No erosion issues observed along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-07610



Inspection Photos  
Location Name: FC Armstrong 001 1  
Location ID: 326180



**Photo 5.** Reference area composed of Sagebrush, Juniper and Blue Grama.