

Inspection Photos

October 22nd, 2024

Operator: Logos Operating LLC -10679

Location ID: 325158

Inspection Document #: 714001381

La Plata County, CO

Township: NESE 10 33N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bondad 33-9 11
Location ID: 325158

10/22/24
324° NW



10/22/24
323° NW

Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Bondad 33-9 11
Location ID: 325158

10/22/24
316° NW



Photo 2. View of the western interim reclamation area composed of Rubber Rabbitbrush and Intermediate Wheatgrass.

Inspection Photos
Location Name: Bondad 33-9 11
Location ID: 325158



Photo 3. View of gully erosion issues that persist along the access road with sediment transport and deposition occurring on the active pad.

Inspection Photos
Location Name: Bondad 33-9 11
Location ID: 325158



Photo 4. Reference area composed of Sagebrush, Juniper and Blue Grama.