

**Operator:** CPR

**Location Name:** OSKARSON E UNIT 62N68W 33SW SW MULTIWELL

**Loc ID:** 322858

**Inspection:** 714300121



**CA:** Unmarked stockpiles were left on location with no liner. No indication if the stockpile is contaminated. BMPs around some soil stockpiles are inadequate. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure.

**CA Resolution:** Operator has reported that the open holes and stockpiles that were previously reported were present only during site decommission operations. All holes have now been backfilled after samples were collected.