

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 10/22/2024



Wellheads – Photo #04363



Separators – Photo #04373



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 10/22/2024



**Tank Battery – Photo #04370**



**Heater Treaters – Photo #04371**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 10/22/2024



Illegible Battery Sign – Photo #04374



Unsecured Separator/Wildlife Entry Hazard – Photo #04372



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 10/22/2024



**Unsecured Separator Separator/Wildlife Entry Hazard –  
Photo #04378**



**Unsecured Separator Separator/Wildlife Entry Hazard –  
Photo #04375**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/MV 23-27

Location ID: 335425

Date: 10/22/2024



**Separator/Wildlife Entry Hazard – Photo #04376**



**Open-Ended Line on Separator – Photo #04377**

