

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 10/23/2024



Location Entrance – Photo #04416



Location – Photo #04417

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 10/23/2024



Location – Photo #04420



Location – Photo #04419

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 10/23/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04418



Sediment Transport Off Site – Photo #04422

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 10/23/2024



Sediment Transport Off Site – Photo #04424