

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403970360

Date Received:  
10/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

9 of 9 CAs from the FIR responded to on this Form

9 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10407

Name of Operator: ANTLER ENERGY LLC

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Evans, Clay	(307) 380-7616	clay@antler-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500631

Inspection Date: 09/10/2024 FIR Submit Date: 09/10/2024 FIR Status:

Inspected Operator Information:

Company Name: ANTLER ENERGY LLC Company Number: 10407

Address: PO BOX 104

City: BAGGS State: WY Zip: 82321

LOCATION - Location ID: 312865

Location Name: POLE GULCH-612N92W Number: 15SWNW County: MOFFAT

Qtrqtr: SWN Sec: 15 Twp: 12N Range: 92W Meridian: 6  
W

Latitude: 40.999330 Longitude: -107.713760

FACILITY - API Number: 05-081-00 Facility ID: 222663

Facility Name: POLE GULCH Number: 6

Qtrqtr: SWN Sec: 15 Twp: 12N Range: 92W Meridian: 6  
W

Latitude: 40.999330 Longitude: -107.713760

CORRECTIVE ACTIONS:

1 CA# 198573

Corrective Action: All load lines or tank valves that can be used as a load line will be capped or plugged. Date: 09/16/2024

Response: CA COMPLETED Date of Completion: 09/11/2024

Operator Comment: All load lines are now plugged and capped.

ECMC Decision:

ECMC  
Representative:

**2** CA# 198574

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 09/26/2024

Response: CA COMPLETED

Date of Completion: 09/12/2024

Operator  
Comment: Oily waste has been removed

ECMC Decision:

ECMC  
Representative:

**3** CA# 198575

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 09/26/2024

Response: CA COMPLETED

Date of Completion: 09/12/2024

Operator  
Comment: Oily waste has been removed

ECMC Decision:

ECMC  
Representative:

**4** CA# 198576

Corrective Action: Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.

Date: 09/18/2024

Response: CA COMPLETED

Date of Completion: 09/13/2024

Operator  
Comment: All weeds cut and removed

ECMC Decision:

ECMC  
Representative:

**5** CA# 198577

Corrective Action: All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.

Date: 09/18/2024

Response: CA COMPLETED

Date of Completion: 09/13/2024

Operator  
Comment: Debris, rubbish, etc has all been removed

ECMC Decision:

ECMC  
Representative:

**6** CA# 198578

Corrective Action:

Date: 10/11/2024

The Wellhead sign will identify: The Well name; The API Number; and Its legal location, including the quarter/quarter section.

Response: CA COMPLETED

Date of Completion: 09/16/2024

Operator  
Comment:

Wellhead sign has all the required info now.

ECMC Decision:

ECMC  
Representative:

**7** CA# 198579

Corrective Action:

The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well (s); and Location, including the quarter/quarter section, of the Tank battery.

Date: 10/11/2024

Response: CA COMPLETED

Date of Completion: 09/13/2024

Operator  
Comment:

Tank battery sign has been installed on the tank stairs.

ECMC Decision:

ECMC  
Representative:

**8** CA# 198580

Corrective Action:

All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.

Date: 09/21/2024

Response: CA COMPLETED

Date of Completion: 09/13/2024

Operator  
Comment:

Wildlife screens installed

ECMC Decision:

ECMC  
Representative:

**9** CA# 198581

Corrective Action:

Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.

Date: 10/11/2024

Response: CA COMPLETED

Date of Completion: 09/26/2024

Operator  
Comment:

Form 2 submitted

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective Actions have been met

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Clay Evans

Signed: \_\_\_\_\_

Title: President

Date: 10/25/2024 10:12:21 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403970360	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files