

Inspection Photos

API: 071-06598

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 10/23/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. There is erosion along the access road northeast of the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing west toward the wellsite.

