

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/34NWNE

Location ID: 324157

Date: 10/23/2024



Location Entrance – Photo #04434



Location – Photo #04435



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/34NWNE

Location ID: 324157

Date: 10/23/2024



Location – Photo #04438



Location – Photo #04440

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/34NWNE

Location ID: 324157

Date: 10/23/2024



Chemical Tank not Labeled – Photo #04436



Chemical Tank not Labeled – Photo #04437



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/34NWNE

Location ID: 324157

Date: 10/23/2024



**Open-Ended Load Line – Photo #04439**

