

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Location – Photo #04448



Location – Photo #04452

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Location – Photo #04455



Condensate Tank Labels Do Not State Tank Capacity – Photo #04458

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Produced Water Tank Labels Do Not State Tank Capacity –
Photo #04459



Stored Supplies in Secondary Containment – Photo #04461

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04450



Open Wellhead Cellar/No Wildlife Egress – Photo #04451

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Open-Ended Line on Storage Tank – Photo #04460



Open-Ended Line on Storage Tank – Photo #04465



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, ExxonMobil/GM 331-34

Location ID: 335336

Date: 10/23/2024



Open-Ended Load Line – Photo #04457