

Final Reclamation and Stormwater Inspection

Date: 10/23/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 331898

Inspection Document #: 713901127

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Newnam #2-32
Location ID: 331898



Photo 1. The photo was taken at the well location facing North. The photo illustrates the well location is dominated by kochia, russian thistle and field bindweed.

Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: Newnam #2-32
Location ID: 331898



Photo 3. The photo was taken at the well location facing South.
Refer to the comment for photo 1.

Photo 4. The photo was taken at the well location facing West.
Refer to the comment for photo 1.

Inspection Photos
Location Name: Newnam #2-32
Location ID: 331898



Photo 5. The photo was taken at the well location facing South. The photo illustrates the boundary of the well location disturbance and reference areas.



Photo 6. The photo was taken at the tank battery location facing East. The photo illustrates the tank battery location remains active for other wells.

Inspection Photos
Location Name: Newnam #2-32
Location ID: 331898



Photo 7. The reference photo was taken west of the well location facing Southwest. The photo illustrates references areas are dominated with saltgrass and other desirable species.