

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Oct 23, 2024 at 2:31:16 PM
CO

Photo # 6967 From entrance to location



Oct 23, 2024 at 2:33:49 PM
CO

Photo # 6968 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Photo # 6969 Location



Photo # 6970 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Photo # 6971 Location



Photo # 6972 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Photo # 6973 Location



Photo # 6974 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Photo # 6975 Location



Photo # 6976 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WELLS RWF 23-32 Pad

Location ID: 334748



Photo # 6977 Location




Photo # 6978 Tank label contains inaccurate information