

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403963677

Date Received:

10/21/2024

Spill report taken by:

Araza, Steven

Spill/Release Point ID:

488230

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECOM Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>LARAMIE ENERGY LLC</u>	Operator No: <u>10433</u>	Phone Numbers
Address: <u>1700 LINCOLN ST STE 3950</u>		Phone: <u>(970) 9019007</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Matt Kasten</u>		Mobile: <u>()</u>
		Email: <u>mkasten@laramie-energy.com</u>

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORTInitial Spill/Release Report Doc# 403956076

Initial Report Date: <u>10/14/2024</u>	Date of Discovery: <u>10/12/2024</u>	Spill Type: <u>Recent Spill</u>
--	--------------------------------------	---------------------------------

Spill/Release Point Location:

QTRQTR NESW SEC 31 TWP 7S RNG 97W MERIDIAN 6

Latitude: 39.403037 Longitude: -108.258539

Municipality (if within municipal boundaries): _____ County: GARFIELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☒ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

Reference Location:

Facility Type: PRODUCED WATER TRANSFER SYSTEM ☒ Facility/Location ID No 469498

Spill/Release Point Name: Cascade 4" PW Release ☐ Well API No. (Only if the reference facility is well) 05- -

☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>0</u>	Estimated Condensate Spill Volume(bbl): <u>0</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>>=5 and <100</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: Clear 70

Surface Owner: FEDERAL Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During pressure testing by air, Laramie's 4" produced water line had a failure. Once the failure was noted on gauges, the test was stopped. It was discovered by Logan Wash road where the hole had free standing fluid. Water hauling company was called to recover fluids. TBD on fluid amount estimate 25 - 35bbls lost that was residual within the line during pressure test. Initial findings of failed line look to be a kink that was weak part. More details to follow on SF19s

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
10/14/2024	CPW	Taylor Elm	-	Email
10/14/2024	Garfield County	Kirby Winn	-	Email
10/14/2024	BLM	GJ ROW	-	Email
10/12/2024	ECMC	Steven Arauza	-	

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: n/a Public Water System: n/a
- Residence or Occupied Structure: n/a Livestock: n/a
- Wildlife: n/a Publicly-Maintained Road: n/a
- Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery _____ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
- Enter the Document Number of the Initial Accident Report, Form 22 _____
- Was there damage during excavation? _____
- Was CO 811 notified prior to excavation? _____
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): _____

No	Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
	<input type="checkbox"/> The presence of free product or hydrocarbon sheen Surface Water <input type="checkbox"/> The presence of free product or hydrocarbon sheen on Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Groundwater <input type="checkbox"/> The presence of contaminated soil in contact with Surface water
No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 10/21/2024		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	35	30	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>100</u>		Width of Impact (feet): <u>100</u>	
Depth of Impact (feet BGS): <u>7</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
TBD - Visual currently. Will be soil sampled for delineation.			
Soil/Geology Description:			
Clay			
Depth to Groundwater (feet BGS) <u>50</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest		Water Well _____ None <input checked="" type="checkbox"/>	Surface Water <u>115</u> None <input type="checkbox"/>
		Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>
		Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building _____ None <input checked="" type="checkbox"/>
Additional Spill Details Not Provided Above:			

Dry drainage noted northwest of project. Expired well noted near site (2,650' SW).

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 10/21/2024

Root Cause of Spill/Release Equipment Failure

Other (specify)

Type of Equipment at Point of Spill/Release: Process Piping

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

Appears from installation that there was a kink in the line is failure point resulting in the rupture. To make the corner, Laramie assumes that they bent line in or/during backfill the line was manipulated in a way to kink.

Describe measures taken to prevent the problem(s) from reoccurring:

Lines will be re-installed per best practices with competent contractors and inspect lines prior to any testing and burial. During repair, line will be place in with less of a angle to avoid any wrongful placement and during backfill after spill cleanup, line will be monitored so no excess dirt moves line out of alignment.

Volume of Soil Excavated (cubic yards): 20

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal Onsite Treatment

☐ Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: _____

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Soil sampling of POR still pending. BLM GJ ROW notice to proceed attached. Pipeline has been repaired. Estimated 20 yards of soil removal will update as tickets from Greenleaf come back. 30bbls removed from trench (Ticket attached).

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Matt Kasten

Title: Environmental Coordinator Date: 10/21/2024 Email: mkasten@laramie-energy.com

<u>COA Type</u>	<u>Description</u>
0 COA	

ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
403963677	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403963688	CORRESPONDENCE
403963689	PHOTO DOCUMENTATION
403963692	PHOTO DOCUMENTATION
403963698	DISPOSAL MANIFEST
403963699	PHOTO DOCUMENTATION
403971499	FORM 19 SUBMITTED

Total Attach: 7 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Comply with outstanding COAs.	10/21/2024

Total: 1 comment(s)