

Inspection Photos

ID: 453010

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the compressor facility. The road was regraded but additional erosion has since occurred.



Inspection Photos



Photo 2. Facing toward the compressor facility. Stormwater erosion is depositing gravel and sediment onto the road. BMP's must be installed to prevent erosion..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:453010 | Date: 10/28/2024