

Inspection Photos  
Location Name: FERGUSON #21-9  
Location ID: 319739



Photo #1 Location sign.



Photo #2 Condensate tank.

**Inspection Photos**  
**Location Name: FERGUSON #21-9**  
**Location ID: 319739**



**Photo #3 Erosion under condensate tank.**



**Photo #4 No access to separator and well head.**