

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/24/2024



South End of Location – Photo #04510



Location – Photo #04511

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/24/2024



Location – Photo #04513



Location – Photo #04512

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3SENW

Location ID: 334882

Date: 10/24/2024



Rill Erosion on Lease Road – Photo #04514



Rill Erosion on Lease Road – Photo #04515