

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 10/24/2024



Location Entrance – Photo #04517



Location – Photo #04518

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 10/24/2024



Location – Photo #04522



Location – Photo #04526

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 10/24/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04519



Open Wellhead Cellar/No Wildlife Egress – Photo #04520

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 10/24/2024



Open Wellhead Cellar/No Wildlife Egress – Photo #04521



Open-Ended Line on Separators – Photo #04523

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/3NWNW

Location ID: 334818

Date: 10/24/2024



Open-Ended Line on Separators – Photo #04524



Open-Ended Lines on Separators – Photo #04525