

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
MAPLEWOOD ACRES 12-7 TB	Oct	Armando Munoz	10/15/2024
Work Summary	Reclamation Type	Land Use	
Remove weeds trash from Location repair rills along ditch pad. Return any sediment to pad	Stormwater	Active Pad	
One-Call Number	Red Zone Rep	Red Zone Date	

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	High	Yes	Location(s): MAPLEWOOD_35-7 Notes: Remove weeds, trash from location, repair rills along ditch and pad, return any sediment to pad.

COMPLETION DETAILS

Total Area Affected: 15,648 sq ft Seed Mix: None used Crop Type: Corn Soil Type: Clay Loam Stabilization Date: 10/15/2024 Seeding Date: Mulch: None Straw Bales: NA Soil Amendment Type: None Soil Amendment Rate: NA Imported Top Soil: NA Top Soil Source: NA General Notes:

PHOTOS

Photo Name: Site Map

Description:



Photo Name: Pre-Completion

Description:

Photo Name: Site Map

Description:




Photo Name: Post-Completion

Description:



Photo Name: MW2

Description:



Photo Name: MW3

Description:



Photo Name: MW4

Description:



Photo Name: MW5

Description:



Photo Name: MW6

Description:



Photo Name: MW7

Description:

