

Inspection Photos

API: 071-06299

Operator: OGRIS OPERATING LLC

Inspection Date: 10/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



October 28, 2024
+37.110434,-104.868467

Photo 2. Facing west toward the well site...



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06299 | Date: 10/28/2024

Inspection Photos



Photo 3. Facing west toward the cut slope. This erosion gully needs to be repaired and stabilized.



Inspection Photos



Photo 4. Facing east at the top of the cut slope. This erosion gully needs to be repaired and stabilized.

