

Final Reclamation and Stormwater Inspection

Date: 10/23/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 318986

Inspection Document #: 713901132

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ruhl #1
Location ID: 318986



Photo 1. The photo was taken at the well location facing North. The photo illustrates the alfalfa field has recently been harvested.

Photo 2. The photo was taken at the well location facing East. Refer to the comment for photo 1.

Inspection Photos
Location Name: Ruhl #1
Location ID: 318986



Photo 3. The photo was taken at the well location facing South. Refer to the comment for photo 1.

Photo 4. The photo was taken at the well location facing West. Refer to the comment for photo 1.



Photo 5. The photo was taken at the tank battery location facing North. The photos illustrate the access road has been removed and the tank battery location remains active for other nearby wells.