

Interim Reclamation and Stormwater Inspection

Date: 10/23/24

Operator: Crestone Peak Resources Operating LLC -
10633

Location ID: 439041

Inspection Document #: 713901138

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ruhl 32H-B264 West
Location ID: 439041



Photo 1. The photo was taken at the entrance to the well location facing West. The photo illustrates tumbleweeds growing along the access road.



Photo 2. The photo was taken at the well location facing Southwest. The photo illustrates tumbleweeds growing along the South side of the well location.

Inspection Photos

Location Name: Ruhl 32H-B264 West

Location ID: 439041



Photo 3. The photo was taken at the well location facing Northwest. The photo illustrates tumbleweeds growing along the North side of the well location.

Photo 4. The photo was taken at the well location facing Northeast. The photo illustrates tumbleweeds growing along the rock/gravel berm.