

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Oct 29, 2024 at 10:55:25
5253 County Road 301
Parachute CO 81635
United States



Oct 29, 2024 at 10:55:58
5253 County Road 301
Parachute CO 81635
United States

East End of Location – Photo #04534

Location – Photo #04535

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Oct 29, 2024 at 10:57:54
5253 County Road 301
Parachute CO 81635
United States

Location – Photo #04540



Oct 29, 2024 at 10:57:28
5253 County Road 301
Parachute CO 81635
United States

Location – Photo #04539

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Oct 29, 2024 at 10:59:30
5253 County Road 301
Parachute CO 81635
United States

Location – Photo #04545



Oct 29, 2024 at 10:57:07
5253 County Road 301
Parachute CO 81635
United States

Location – Photo #04538

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Wildlife Entry Hazard – Photo #04541



Wildlife Entry Hazard – Photo #04542

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Lack of Stabilization/Degradation – Photo #04537



Lack of Stabilization/Degradation – Photo #04546

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GRAND VALLEY RANCH CO-67S95W/1SWSE

Location ID: 334734

Date: 10/29/2024



Insufficient Tracking BMPs – Photo #04547