

Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Photo # 8206 Near entrance to location



Photo # 8207 Location

Inspection Photos
Location: QB ENERGY Puckett/697-26A
Location ID: 416157
Date: 10/29/2024



Oct 29, 2024 at 1:15:47 PM
+39.498851,-108.183024 ±4.74m
Parachute

Photo # 8208 Location



Oct 29, 2024 at 1:16:17 PM
+39.498851,-108.183024 ±4.74m
Parachute

Photo # 8209 Location

Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Oct 29, 2024 at 1:25:28 PM
+39.498853,-108.182986 ±4.74m
Parachute

Photo # 8229 Location



Oct 29, 2024 at 1:30:33 PM
+39.499128,-108.182850 ±4.73m
Parachute

Photo # 8232 Location



Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Photo # 8237 Location



Photo # 8242 Location



Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Photo # 8262 SW corner of location



Photo # 8263 SE corner of location

Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Oct 29, 2024 at 1:52:36 PM
+39.499095,-108.183097 ±4.72m
Parachute

Photo # 8275 NW corner of location



Oct 29, 2024 at 1:22:12 PM
+39.498752,-108.183010 ±4.74m
Parachute

Photo # 8217 Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill

Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Photo # 8220 Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill



Photo # 8221 Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill

Inspection Photos

Location: QB ENERGY Puckett/697-26A

Location ID: 416157

Date: 10/29/2024



Photo # 8227 Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill



Photo # 8269 Barbed wire/wildlife hazard

Inspection Photos
Location: QB ENERGY Puckett/697-26A
Location ID: 416157
Date: 10/29/2024



Photo # 8272 Barbed wire/wildlife hazard



Photo # 8280 Barbed wire/wildlife hazard