

Inspection Photos

October 28th, 2024

Operator: Rim Operating - 74650

Location ID: 306961

Inspection Document #: 714001401

La Plata County, CO

Township: SWNE 36 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pargin Ranch 1
Location ID: 306961



Photo 1. View of the well disturbance taken from the northern edge facing center.



API #: 067-09185

Inspection Photos
Location Name: Pargin Ranch 1
Location ID: 306961



Photo 2. View of both the southern and eastern interim reclamation areas which remain dominated by weedy Kochia debris.