

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8096 Entrance to location



Photo # 8117 Location



Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8098 Location



Photo # 8099 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Oct 28, 2024 at 11:37:12 AM
+39.503343,-108.174143 ±4.73m

Photo # 8110 Location



Oct 28, 2024 at 11:45:19 AM
+39.503043,-108.174249 ±4.72m

Photo # 8114 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8115 Location



Photo # 8127 Location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8136 NE corner of location



Photo # 8137 SE corner of location

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8139 NW corner of location



Photo # 8129 Barbed wire/wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8130 Barbed wire/wildlife hazard



Photo # 8132 Barbed wire/wildlife hazard

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8133 Barbed wire/wildlife hazard



Photo # 8134 Debris

Inspection Photos

Location: QB ENERGY PUCKETT-66S97W/24SWSW

Location ID: 335528

Date: 10/28/2024



Photo # 8135 Debris



Photo # 8138 Debris