

**Operator: *Crestone Peak Resources Operating LLC***

**Location Name: ANNIS-62N65W 24NWSE**

**Loc ID: 323195**

**Inspection: 714201777**



Exhibit A

**CA:** H2O BBLs are not legible. See attached photo. Install sign to comply with Rule 605.h

**CA Resolution:** Operator has added tank volume to the fiberglass water tank in order to comply with Rule 606.