

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582




Photo 1: Location from entrance

Photo 2: Tank Battery Sign

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Photo 3: Tank Battery, H2O tank damaged

Photo 4: Equipment

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582





Photo 5: Wellhead Sign

Photo 6: TA Wellhead

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Photo 7: Overgrown vegetation