

Inspection Photos  
Location Name: Musick-McClintock #7  
Location ID: 311364



Photo 1: Pumpjack sign, Operator Name not legible

Photo 2: Overgrown vegetation

**Inspection Photos**  
**Location Name: Musick-McClintock #7**  
**Location ID: 311364**



**Photo 3: Overgrown vegetation**

**Photo 4: Unused equipment**

**Inspection Photos**  
**Location Name: Musick-McClintock #7**  
**Location ID: 311364**



**Photo 5: Overgrown vegetation**

**Photo 6: Overgrown vegetation**