



Inspection Photos
Location Name: Cascade 4" PW Release
Spill/Release ID: 488230
Inspection Date: October 17, 2024

Spill/Release area.

Oct 17, 2024 11:59:22 AM
+39.4029N -108.2584W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Excavation of Laramie's 4" produced water line that had failed. Note the livestock fencing on the northwest side of the excavation.

Oct 17, 2024 11:59:39 AM
+39.4030N -108.2585W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Excavation of Laramie's 4" produced water line that had failed. Note the livestock fencing on the northwest side of the excavation and the potentially impacted fluids within the excavation.

Oct 17, 2024 12:00:01 PM
+39.4031N -108.2586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Excavation of Laramie's 4" produced water line that had failed. Note the potentially impacted fluids within the excavation.

Oct 17, 2024 12:00:10 PM
+39.4031N -108.2586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Stockpiles of potentially impacted material.

Oct 17, 2024 12:01:13 PM
+39.4031N -108.2586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Stockpiles of potentially impacted material.

Oct 17, 2024 12:01:55 PM
+39.4029N -108.2584W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Stockpiles of potentially impacted material.

Oct 17, 2024 12:00:20 PM
+39.4031N -108.2586W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Cascade 4" PW Release

Spill/Release ID: 488230

Inspection Date: October 17, 2024

Stockpile of potentially impacted material.

Oct 17, 2024 12:01:28 PM
+39.3191N -108.2098W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources