

# Inspection Photos

10/31/2024

**Operator:** GUNNISON ENERGY LLC #10515

**Location ID:** 324485

**Inspection Doc:** 696206402

Gunnison County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



**Photo 1:** Photos taken from the south end of the Location. Photos provide an overview of the Location west to northwest. All wells on the Location have been plugged. Location is now subject to 1004 Requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



**Photo 2:** Photos examples showing excavations missing required fencing, and stockpiled soils missing BMPs pursuant to Rules 1002.c and 1002.f. Photo also shows various pipe remaining on Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



**Photo 4:** See comments under photo 2. Pipe/Equipment requires removal pursuant to 1004 requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources