

**Storm Water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC State of Colorado KP 32-9 Pad**  
**Location ID: 435118**



**Location Overview: Location is within High Priority/Density/NSO/Black Bear Habitat areas & in close proximity Bald Eagle Nest & Roost sites. Location is approximately 121 yards from Garfield Creek.**

**Section/Township/Range: 9 6S91W**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC State of Colorado KP 32-9 Pad**  
**Location ID: 435118**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: TEP ROCKY MOUNTAIN LLC State of Colorado KP 32-9 Pad**  
**Location ID: 435118**



**Photo # 7270 Large amount of sediment buildup at culvert outlet/capacity reduced/may need maintenance in near future**



**Photo # 7271 Large amount of sediment buildup at culvert outlet/capacity reduced/may need maintenance in near future**