

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 10/30/2024




Photo # 8284 Entrance to location




Photo # 8292 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 10/30/2024



Oct 30, 2024 at 10:25:40 AM
+39.411372,-108.098236 ±4.71m
De Beque

Photo # 8285 Location



Oct 30, 2024 at 10:28:14 AM
+39.411714,-108.098523 ±4.72m
De Beque

Photo # 8289 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC WRIGHT,SMALLWOOD,CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 10/30/2024



Photo # 8291 Location



Photo # 8297 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC WRIGHT, SMALLWOOD, CASTEEL-67S96W/27SENW

Location ID: 334744

Date: 10/30/2024



Photo # 8298 NW corner of location

