

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad

Location ID: 335604



Photo # 8394 From entrance to location



Photo # 8395 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad

Location ID: 335604



Photo # 8396 Location



Photo # 8397 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad

Location ID: 335604



Photo # 8398 Location



Photo # 8399 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad

Location ID: 335604



Photo # 8400 Location




Photo # 8401 Tank label lacks capacity/does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 169-18 Pad

Location ID: 335604



Photo # 8402 Improperly marked deadman



Photo # 8403 Same improperly marked deadman