

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SAVAGE-67S95W/20SESE

Location ID: 334996

Date: 10/31/2024



Location Entrance – Photo #04658



Location – Photo #04660

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SAVAGE-67S95W/20SESE

Location ID: 334996

Date: 10/31/2024



Location – Photo #04662



Location – Photo #04659

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SAVAGE-67S95W/20SESE

Location ID: 334996

Date: 10/31/2024



Location – Photo #04663



Lack of Stabilization – Photo #04661

Inspection Photos

Location Name: CAERUS PICEANCE LLC, SAVAGE-67S95W/20SESE

Location ID: 334996

Date: 10/31/2024



Insufficient Tracking BMPs – Photo #04664