

Operator: *CRESTONE PEAK RESOURCES OPERATING LLC*

Location Name: Ruhl 32H-B264 West

Loc ID: 439041

Inspection: 713901138



Exhibit A

CA: Weed debris in the form of tumbleweeds were observed along the boundary of the well location and on the irrigation berms of the well location. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606 to remove weed debris.

CA Resolution: Operator has addressed the weed debris issue, property has been mowed as well in order to comply with Rule 606.