

Work Completion Report

Contractor: US Hydro

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
JEFFERS #1 (2024 SEASONAL)	Oct	Brian Schoenecker	10/25/2024

Work Summary	Reclamation Type	Land Use
Met with Drew on site. Cross Innerseed site. Rake up eroded soil and fill rills. Scott brought in a little topsoil to finish filling in and capping rills. Raked rolls level and seed over. Hand seed along fence lines.	Final Maint	Pasture

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Reclamation Maintenance	High	Yes	Location(s): JEFFERS #1 Notes: Repair rills on location with rake, innerseed area with smooth brome. This is a ECMC CA. Please call DS prior to work.

COMPLETION DETAILS

Total Area Affected: 30,492 sq ft Seed Mix: Smooth brome (40.00 lbs) Crop Type: Soil Type: Clay Loam Stabilization Date: Seeding Date: 10/25/2024 Mulch: None Straw Bales: NA Soil Amendment Type: None Soil Amendment Rate: NA Imported Top Soil: NA Top Soil Source: NA General Notes:
--

PHOTOS

Photo Name: Seed Mix
Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Rills

Description:



Photo Name: Fill in rills

Description:



Photo Name: Filled in rill
Description:

