

Inspection Photos

October 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333539

Inspection Document #: 714001420

La Plata County, CO

Township: SWNW 34 33N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Moffett B1
Location ID: 333539



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Moffett B1
Location ID: 333539



Photo 2. No weeds/weedy debris observed around the well head.

Inspection Photos
Location Name: Moffett B1
Location ID: 333539



Photo 3. Musk Thistle observed along the western edge of the disturbance.

Inspection Photos
Location Name: Moffett B1
Location ID: 333539



Photo 4. Produced water tank secondary containment/berm has been compromised by Burrows and erosion and is not longer functioning to its full capacity.

Inspection Photos
Location Name: Moffett B1
Location ID: 333539



Photo 5. Active pasture reference area.