

Final Reclamation Inspection

October 21, 2024

Operator: TOP OPERATING COMPANY - 39560

Location ID: 319067

Inspection Document #: 697505543

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 1. Photo taken on June 9, 2022 from the northwestern location, facing South. Photo illustrates all equipment has been removed from location and final reclamation has been completed. Desirable vegetation was observed throughout the disturbance area.



Photo 2. Photo taken on October 21, 2024 from the central location, facing West. Photo illustrates location is progressing with desirable perennial vegetation.

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 3. Photo taken on June 9, 2022 from the northern location, facing East. See comments under Photo 1.



Photo 4. Photo taken on October 21, 2024 from the central location, facing East. Photo illustrates the northern location lacks desirable establishment due to recontouring flood irrigation issues.

City of Longmont (surface owner) is looking into recontouring or seeding the northern area as a rangeland seed mixture.

Inspection Photos
Location Name: STAMP #31-2C
Location ID: 319067



Photo 5. Photo taken on October 21, 2024 from the north location, facing Southeast. See comments under Photo 4. Photo also illustrates reference area vegetation compared to the northern location.